

1 Cut hole in ceiling.





2 Connect luminaire to driver. Place the luminaire.



Use constant currrent driver with strain relief.

Always check polarity and max drive current.

max 350 mA 33	8.5V I	2 W